



DIN 562

Nakrętki kwadratowe



| d | m | s | e | □ |
|------|-----|-----|------|-----|
| M1,6 | 1,0 | 3,2 | 4,0 | 3,2 |
| M2 | 1,2 | 4 | 5,0 | 4 |
| M2,5 | 1,6 | 5 | 6,3 | 5 |
| M3 | 1,8 | 5,5 | 7,0 | 5,5 |
| M4 | 2,2 | 7 | 8,9 | 7 |
| M5 | 2,7 | 8,9 | 10,2 | 8 |
| M6 | 3,2 | 10 | 12,7 | 10 |
| M8 | 4,0 | 13 | 16,5 | 13 |
| M10 | 5,0 | 16 | 20,2 | 16 |

| Material | Opakowanie |
|----------|------------|
| A2 / A4 | 500 |
| A2 / A4 | 500 |
| A2 / A4 | 500 |
| A2 / A4 | 500 |
| A2 / A4 | 500 |
| A2 / A4 | 500 |
| A2 / A4 | 200 |
| A2 / A4 | 200 |
| A2 / A4 | 100 |