


RX 9326

Nakrętki do zgrzewania typ C



d1	z gwintem	d	h	b
4,1	M3,5	17	5,0	9
4,9	M4	17	6,0	9
6,1	M5	19	7,5	11
7,0	M6	19	7,5	11
7,5	M6	22	8,5	14
9,0	M8	22	8,5	14
9,7	M8	26	10,4	18
11,5	M10	26	11,0	18

Material	Opakowanie
A2	100
A2	100
A2	100
A2	100
A2	100
A2	100
A2	100
A2	100