


RX 9448

Śruby hakowe



| d | d2 | l | w | b |
|----|-----|----|----|----|
| M4 | 3,5 | 40 | 12 | 20 |
| M4 | 3,5 | 50 | 16 | 25 |
| M5 | 4,4 | 50 | 16 | 23 |
| M5 | 4,4 | 60 | 16 | 30 |
| M6 | 5,2 | 50 | 18 | 20 |
| M6 | 5,2 | 60 | 18 | 30 |
| M8 | 7,0 | 70 | 22 | 32 |
| M8 | 7,0 | 80 | 22 | 42 |

| Material | Opakowanie |
|----------|------------|
| A2 | 100 |
| A2 | 100 |
| A2 | 100 |
| A2 | 100 |
| A2 | 100 |
| A2 | 100 |
| A2 | 100 |
| A2 | 100 |