




RX 9612
Śrubunek



d	l	NW	SW
1/4"	45	8	35
3/8"	45	10	38
1/2"	43	15	42
3/4"	46	20	49
1"	51	25	60
1 1/4"	56	32	70
1 1/2"	59	40	77
2"	67	50	91

Material	Opakowanie
A4	1
A4	1
A4	1
A4	1
A4	1
A4	1
A4	1
A4	1

RX 9612 A
Śrubunek





d	l	NW	SW
1/4"	54	8	35
3/8"	57	10	38
1/2"	55	15	42
3/4"	62	20	49
1"	69	25	60
2"	89	50	91

Material	Opakowanie
A4	1
A4	1
A4	1
A4	1
A4	1
A4	1

RX 9612 S

Śrubunek



d	l	NW	SW
3/8"	43	10	38
1/2"	43	15	42
1"	50	25	60
1 1/4"	53	32	70
1 1/2"	70	40	77
2"	75	50	91

Material	Opakowanie
A4	1
A4	1
A4	1
A4	1
A4	1
A4	1